

Client Name:

Inspection Date:

Platform Name:

Inspection Item:

ARE ELECTRICAL INSTALLATIONS MADE IN ACCORDANCE WITH API RP 500 AND API RP 14F OR API RP 505 AND API RP 14FZ?

Comments:

THE ELECTRICAL CONNECTION UNDER THE HELIPORT IS NOT PROPERLY TERMINATED.

Date Corrected

Corrected By (Name):



Corrective Action:

Citation Reference:

F-108

Inspection Item:

IS EACH COMPLETION IDENTIFIED AS REQUIRED AT THE WELLHEAD?

Comments:

WELL A-17 DOES NOT HAVE A WELL IDENTIFICATION SIGN.

Date Corrected

Corrected By (Name):



Corrective Action:

Citation Reference:

G-101

Client Name:

Inspection Date:

Platform Name:

Inspection Item:

DOES THE LESSEE PROVIDE FOR THE SAFETY OF ALL PERSONNEL AND TAKE ALL NECESSARY PRECAUTIONS TO CORRECT AND REMOVE ANY HAZARDOUS OIL AND GAS ACCUMULATION OR OTHER HEALTH, SAFETY, OR FIRE HAZARDS?

Comments:

THE DRIP PAN ON THE M-9 COMPRESSOR HAS STANDING OIL.

Date Corrected

Corrected By (Name):

Corrective Action:

Citation Reference:

G-112



Inspection Item:

ARE SKID-MOUNTED EQUIPMENT, PORTABLE CONTAINERS, SPOOLS OR REELS, AND DRUMS CLEARLY MARKED WITH THE OWNER'S NAME WITH A MEDIA DURABLE ENOUGH TO RESIST THE EFFECTS OF THE ENVIRONMENTAL CONDITIONS?

Comments:

THE WARNING LABELS ON THE CHEMICAL TANKS ARE NEITHER VISIBLE NOR ACCESSIBLE.

Date Corrected

Corrected By (Name):

Corrective Action:

Citation Reference:

G-251



Client Name:

Inspection Date:

Platform Name:

Inspection Item:

PROBABILITY THAT EYE INJURY MAY OCCUR.

Comments:

THERE IS A MISSING EYE WASH STATION; CHLORINE AND BATTERIES ARE PRESENT.

Date Corrected

Corrected By (Name):



Corrective Action:

Citation Reference:

Z-110

Inspection Item:

IS A WELL-MAINTAINED, APPROVED TYPE I LIFE PRESERVER PROVIDED FOR EACH PERSON AND STORED IN AN EASILY ACCESSIBLE LOCATION ON A MANNED OCS PLATFORM?

Comments:

IN THE LIFE JACKET CONTAINER LOCATED NEAR THE DIESEL TANK, TWO OF THE LIFE JACKET'S HAVE LIGHTS WITHOUT VISIBLE EXPIRATION DATES.

Date Corrected

Corrected By (Name):



Corrective Action:

Citation Reference:

Z-150